

The Joint Apprenticeship Training Committee class schedule and enrollment process are listed below:

Location: Plumbers & Pipefitters Training Center
411 Arizona SE
Albuquerque, NM 87108

Enrollment: Contact the Training Center at (505) 256-9257 between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday to sign up for a class or to request a registration form. **Sign up is REQUIRED for all classes.**

 OCTOBER 2026 						
<u>Sunday</u>	<u>Monday</u>	<u>Tuesday</u>	<u>Wednesday</u>	<u>Thursday</u>	<u>Friday</u>	<u>Saturday</u>
				<u>October 1</u>	<u>October 2</u> ** OW Sign Ups End at 2:00pm	<u>October 3</u> Plumbing CEU – Online (8:00am) <u>Open Weld - (8:00am–3:00pm)</u>
<u>October 4</u>	<u>October 5</u>	<u>October 6</u>	<u>October 7</u>	<u>October 8</u>	<u>October 9</u> <u>Union Meeting</u>	<u>October 10</u> Mechanical CEU– Online (8:00am) UA-71 Specialty Training (8:00am-3:30pm) *Pre-requisite required* Solvent Welding (8:00am-3:00pm) Solvent Retest (12:00pm-3:00pm) Tutoring- Gas fitting, Plumbing, Pipefitting (8:00am-2:00pm)
<u>October 11</u>	<u>October 12</u> PVDF → (5:00pm–8:00pm) Orbital → (5:00pm–9:00pm)	<u>October 13</u> PVDF → (5:00pm–8:00pm) Orbital → (5:00pm–9:00pm)	<u>October 14</u> PVDF → (5:00pm–8:00pm) Orbital → (5:00pm–9:00pm)	<u>October 15</u> PVDF → (5:00pm–8:00pm) Orbital → (5:00pm–9:00pm) ** OW Sign Ups End at 2:00pm	<u>October 16</u> PVDF → END (5:00pm–8:00pm) Orbital → (5:00pm–9:00pm) <u>Open Weld- (5:00pm – 9:00pm)</u>	<u>October 17</u> NM Plumbing CEU – EL PASO (8:00am–5:00pm) Journeyman Refrigeration Test Prep (8:00am-3:00pm) Plumbing CEU– In Person (8:00am–5:00pm) HEATS ON
<u>October 18</u>	<u>October 19</u> Orbital → (5:00pm–9:00pm)	<u>October 20</u> Orbital → (5:00pm–9:00pm)	<u>October 21</u> Orbital → (5:00pm–9:00pm)	<u>October 22</u> Orbital → (5:00pm–9:00pm) ** OW & BP Sign Ups End at 2:00pm	<u>October 23</u> Orbital →END (5:00pm–9:00pm) <u>Braze/Solder/R78 Practice (9:00am - 8:00pm)</u> <u>Open Weld- (5:00pm – 9:00pm)</u> ** All Class Sign Ups For 10/24 End at 2:00pm	<u>October 24</u> Orbital Continuity & Retest (8:00am) <u>Braze Test (8:00am-12:00pm)</u> Refrigeration 101 (8:00am) <u>UA Weld Test (8:00am)</u> Correspondence
<u>October 25</u>	<u>October 26</u>	<u>October 27</u> Tube Bending→ (5:00pm-9:00pm)	<u>October 28</u>	<u>October 29</u> Tube Bending→ END (5:00pm-9:00pm)	<u>October 30</u>	<u>October 31</u> HAPPY HALLOWEEN! 