


The Joint Apprenticeship Training Committee class schedule and enrollment process are listed below:

Location: Plumbers & Pipefitters Training Center  
 411 Arizona SE  
 Albuquerque, NM 87108  
 Phone: (505) 256-9257  
 Fax: (505) 255-9688  
 Email: info@jatc412.com

Enrollment: Contact the Training Center at (505) 256-9257 between the hours of 8:00 a.m. and 4:30 p.m., Monday **through Friday to sign up for a class. CLASS DATES SUBJECT TO CHANGE.**

February 2021						
Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday
	<b>Feb 1</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>Rigging &amp; Signaling - ABQ</u> (5:00 - 9:00 pm)	<b>Feb 2</b>  <u>Rigging &amp; Signaling - ABQ</u> (5:00 - 9:00 pm)	<b>Feb 3</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>Rigging &amp; Signaling - ABQ</u> (5:00 - 9:00 pm)	<b>Feb 4</b>  <u>Rigging &amp; Signaling -ABQ</u> (5:00 - 9:00 pm)	<b>Feb 5</b>	<b>Feb 6</b> <u>JM Welding - ABQ</u> (8:00 am – 3:00 pm) D. Carlston Formally Open Welding must sign up  <u>NM Plumbing CEU – Online</u>
<b>Feb 7</b>	<b>Feb 8</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>PVDF – ABQ→</u> (6:00 pm – 9:00 pm)	<b>Feb 9</b>	<b>Feb 10</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>PVDF – ABQ - END</u> (6:00 pm – 9:00 pm)	<b>Feb 11</b>	<b>Feb 12</b>	<b>Feb 13</b> <u>JM Welding - ABQ</u> (8:00 am – 3:00 pm) D. Carlston Formally Open Welding must sign up  <u>Solvent Welding -ABQ</u> (8:00 am – 4:30 pm) L.Necoechea  <u>Tube Bending – ABQ</u> (8:00 am – 5:00 pm)  <u>Pipefitting Code Tutoring – ABQ</u> (8:00 am – 2:00 pm)
<b>Feb 14</b>	<b>Feb 15</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>Backflow – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 16</b>  <u>Orbital Welding – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 17</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>Orbital Welding – ABQ→</u> (5:00 pm – 9:00 pm)  <u>Backflow – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 18</b>  <u>Orbital Welding – ABQ→</u> (5:00 pm – 9:00 pm)  <u>Backflow – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 19</b>	<b>Feb 20</b> <u>NM Mechanical CEU – Online</u>  <u>JM Welding - ABQ</u> (8:00 am – 3:00 pm) D. Carlston Formally Open Welding must sign up <u>Orbital Welding – ABQ→</u> (8:00 am – 5:00 pm)  <u>Backflow – ABQ→</u> (8:00 am – 5:00 pm)
<b>Feb 21</b>	<b>Feb 22</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>Backflow – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 23</b>  <u>Orbital Welding – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 24</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders  <u>Orbital Welding – ABQ→</u> (5:00 pm – 9:00 pm)  <u>Backflow – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 25</b>  <u>Orbital Welding – ABQ→</u> (5:00 pm – 9:00 pm)  <u>Backflow – ABQ→</u> (5:00 pm – 9:00 pm)	<b>Feb 26</b> <u>JM Welding – ABQ</u> (2:00 pm – 8:00 pm) Formally Open Welding must sign up	<b>Feb 27</b> <u>UA Weld Test – ABQ</u> (7:30 am – 3:00 pm)  <u>Orbital Welding – ABQ - END</u> (8:00 am – 5:00 pm)  <u>Backflow – ABQ - END</u> (8:00 am – 5:00 pm)  <b>Apprentice Make-Up &amp; Correspondence</b>
<b>Feb 28</b>	<b>Feb 29</b> <u>Open Welding – FARM</u> (5:00 pm – 8:30 pm) V. Sanders					