

The Joint Apprenticeship Training Committee class schedule and enrollment process are listed below:

Location: Plumbers & Pipefitters Training Center
411 Arizona SE
Albuquerque, NM 87108

Enrollment: Contact the Training Center at (505) 256-9257 between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday to sign up for a class or to request a registration form. **Sign up is REQUIRED for all classes.**

| May 2026 | | | | | | |
|-----------------|---|--|--|---|---|---|
| Sunday | Monday | Tuesday | Wednesday | Thursday | Friday | Saturday |
| <u>April 26</u> | <u>April 27</u> | <u>April 28</u> | <u>April 29</u> **Last Day For Online Plmb CEU Sign Up | <u>April 30</u> **Last Day For Orbital and 5/02 OW Sign Up | <u>May 1</u> | <u>May 2</u> Plumbing CEU – Online (8:00am) Open Weld (OW) Practice (8:00am–3:00pm) |
| <u>May 3</u> | <u>May 4</u> | <u>May 5</u> | <u>May 6</u> **Last Day For Online Mechanical CEU and MEDGAS Recert Sign Ups | <u>May 7</u> 5th Yr Contest **Last Day For 5/09 OW Sign Up | <u>May 8</u> 5th Yr Contest Lunch (12:00pm-2:00pm) **NO UNION** MEETING | <u>May 9</u> Mechanical CEU– Online (8:00am) Mechanical CEU– In Person (8:00am–5:00pm) Tutoring–Gas fitting, Plumbing, Pipefitting, HVAC (8:00am-2:00pm) Open Weld (OW) Practice (8:00am - 3:00pm) |
| <u>May 10</u> | <u>May 11</u> | <u>May 12</u> | <u>May 13</u> **Last Day For 5/15 OW, BSP Sign Ups | <u>May 14</u> | <u>May 15</u> Open Weld (OW) Practice (8:00am–9:00pm) Braze/Solder Practice (BSP) (8:00am-9:00pm) **Last Day For Tube Bending Sign Up | <u>May 16</u> NM Mechanical CEU– El Paso- In Person (8:00am–5:00pm) Solvent Welding (8:00am-3:00pm) Solvent Retest (12:00pm-3:00pm) Basic Electricity (8:00am-12:00pm) **Make Up (8:00am–3:30pm) |
| <u>May 17</u> | <u>May 18</u> PVDF → (5:00pm–8:00pm) | <u>May 19</u> PVDF → (5:00pm–8:00pm) Tube Bending→ (5:00pm-9:00pm) | <u>May 20</u> PVDF → (5:00pm–8:00pm) | <u>May 21</u> PVDF → (5:00pm–8:00pm) Tube Bending→ (5:00pm-9:00pm) | <u>May 22</u> PVDF → (5:00pm–8:00pm) | <u>May 23</u> |
| <u>May 24</u> | <u>May 25</u> *Memorial Day* **Training Center Closed** | <u>May 26</u> | <u>May 27</u> **Last Day For 5/29 OW and BSP Sign Up | <u>May 28</u> | <u>May 29</u> Open Weld (OW) Practice (8:00am–9:00pm) Braze/Solder Practice (BSP) (8:00am-9:00pm) MedGas Recert Class (1:00pm-5:00pm) | <u>May 30</u> Braze Test (8:00am-12:00pm) Orbital Continuity & Retest (8:00am) UA WELD TEST (8:00am) EPA 608 Testing (8:00am) A2L Testing (8:00am) MedGas Recert Test (8:00pm) **Correspondence (8:00am-4:30pm) |
| <u>May 31</u> | | | | | | |