

The Joint Apprenticeship Training Committee class schedule and enrollment process are listed below:

Location: Plumbers & Pipefitters Training Center  
411 Arizona SE  
Albuquerque, NM 87108

Enrollment: Contact the Training Center at (505) 256-9257 between the hours of 8:00 a.m. and 4:30 p.m., Monday through Friday to sign up for a class or to request a registration form. **Sign up is REQUIRED for all classes.**

<b>June 2026</b>						
<u>Sunday</u>	<u>Monday</u>	<u>Tuesday</u>	<u>Wednesday</u>	<u>Thursday</u>	<u>Friday</u>	<u>Saturday</u>
<u>May 31</u>	<u>June 1</u>	<u>June 2</u> <u>Open Weld (OW)</u> <u>(5:00pm-9:00pm)</u>	<u>June 3</u> <u>Open Weld (OW) El Paso</u> <u>(4:30pm-8:30pm)</u>  <b>**Last Day For Online Plmb CEU Sign Up</b>	<u>June 4</u> <u>Open Weld (OW)</u> <u>(5:00pm-9:00pm)</u>  <b>**Last Day For Orbital &amp; PVDF Sign Up</b>	<u>June 5</u>	<u>June 6</u> <u>Plumbing CEU – Online (8:00am)</u>  <u>Journeyman Refrigeration Test Prep (8:00am)</u>  <b>**Make Up (8:00am-3:30pm)</b>
<u>June 7</u>	<u>June 8</u> <u>PVDF → (5:00pm-8:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>	<u>June 9</u> <u>PVDF → (5:00pm-8:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>	<u>June 10</u> <u>PVDF → (5:00pm-8:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>  <u>Open Weld (OW) El Paso (4:30pm-8:30pm)</u>  <b>**Last Day For Online Mech CEU Sign Up</b>	<u>June 11</u> <u>PVDF → (5:00pm-8:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>  <b>**Last Day For Solvent &amp; Plmb CEU Sign Up</b>	<u>June 12</u> <u>PVDF → (5:00pm-8:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>  <b>**Union Meeting</b>	<u>June 13</u> <u>Mechanical CEU– Online (8:00am)</u>  <u>Plumbing CEU– In Person (8:00am-5:00pm)</u>  <u>Solvent Welding (8:00am-3:00pm)</u>  <u>Solvent Retest (12:00pm-3:00pm)</u>  <u>Tutoring-Gas fitting, Plumbing, Pipefitting, HVAC (8:00am-2:00pm)</u>  <u>Open Weld (OW) (8:00am - 3:00pm)</u>
<u>June 14</u>	<u>June 15</u>  <u>Orbital → (5:00pm-9:00pm)</u>  <b>**Last Day For Backflow Sign Up</b>	<u>June 16</u>  <u>Orbital → (5:00pm-9:00pm)</u>	<u>June 17</u> <u>Backflow → (5:00pm-9:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>  <u>Open Weld (OW) (5:00pm-9:00pm)</u>  <u>Open Weld (OW) El Paso (4:30pm-8:30pm)</u>	<u>June 18</u> <u>Backflow → (5:00pm-9:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>  <b>**Last Day For Specialty Class (6/20) Sign Up</b>	<u>June 19</u> <u>Backflow → (5:00pm-9:00pm)</u>  <u>Orbital → (5:00pm-9:00pm)</u>  <u>Open Weld (OW) (8:00am-9:00pm)</u>  <u>Braze/Solder Practice (BSP) (8:00am-9:00pm)</u>  <b>**Last Day For Tube Bending Sign Up</b>	<u>June 20</u> <u>Backflow → (8:00pm-4:00pm)</u>  <u>Specialty Class- Pipefitting- 57 1/4 No Math Layout (8:00am)</u>
<u>June 21</u>	<u>June 22</u>	<u>June 23</u>  <u>Tube Bending→ (5:00pm-9:00pm)</u>	<u>June 24</u> <u>Backflow → (5:00pm-9:00pm)</u>	<u>June 25</u> <u>Backflow → (5:00pm-9:00pm)</u>  <u>Tube Bending→ (5:00pm-9:00pm)</u>	<u>June 26</u> <u>Backflow → (5:00pm-9:00pm)</u>  <u>Open Weld (OW) (8:00am-9:00pm)</u>  <u>Braze/Solder Practice (BSP) (8:00am-9:00pm)</u>	<u>June 27</u> <u>Backflow → (8:00pm-4:00pm)</u>  <u>Braze Test (8:00am-12:00pm)</u>  <u>Orbital Continuity &amp; Retest (8:00am)</u>  <u>UA WELD TEST (8:00am)</u>
<u>June 28</u>	<u>June 29</u>	<u>June 30</u>				